

ABSTRACT:

A method of forming a flange on a circular metal blank (1) has the following steps:

- By means of at least one pressure roller (3), a hub-type and/or conical structure is formed on the circular metal blank, and
- from the conical structure (4), a flange (7) is formed on the circular metal blank (1) by means of a subsequent treatment.

Figure 3